


6 axis step motor controller
with 32 general I/O's control

babakmanafi@yahoo.com

Digital Inputs		Digital Outputs	
Mega pin #	Input #	Mega pin #	Output #
Pin 22	In 01	Pin 23	Out 01
Pin 24	In 02	Pin 25	Out 02
Pin 26	In 03	Pin 27	Out 03
Pin 28	In 04	Pin 29	Out 04
Pin 30	In 05	Pin 31	Out 05
Pin 32	In 06	Pin 33	Out 06
Pin 34	In 07	Pin 35	Out 07
Pin 36	In 08	Pin 37	Out 08
Pin 38	In 09	Pin 39	Out 09
Pin 40	In 10	Pin 41	Out 10
Pin 42	In 11	Pin 43	Out 11
Pin 44	In 12	Pin 45	Out 12
Pin 46	In 13	Pin 47	Out 13
Pin 48	In 14	Pin 49	Out 14
Pin 50	In 15	Pin 51	Out 15
Pin 52	In 16	Pin 53	Out 16

Digital input or Ref. switch setup



Emergency shut down

